

## FO Sensor Systems

Four sensor system configurations can be produced:

1. **One Part System** - the fiberoptic cable is not detachable from the amplifier.
2. **Two Part System** - has a cable-mounted or amplifier bulkhead-mounted connector.
3. **Three Part Vacuum Passthru System** - has a separate vacuum passthru flange.
4. **Three Part Extension Cable System** - has two in-line cable connectors.

